


KDR-TC-41-(W寸法)

中量用



$W=300\sim 1000$ (100とび)

(単位 : mm)